

**REED Instruments** 

 $1\text{-}877\text{-}849\text{-}2127 \mid \text{info@reedinstruments.com} \mid \text{www.reedinstruments.com}$ 

## **Table of Contents**

Introduction	2
Product Quality	3
Safety	3
Features	4
Specifications	4-5
Included	5
Instrument Description	6
Display Description	6
Operating Instructions	7-8
Unit of Measure Selection (Temperature)	7
Data Hold	7
Setting the Alarm Threshold	7
MAX Function	8
Auto Power Off	8
Backlight	8
Beeper Off	8
Battery Replacement	9
Accessories and Replacement Parts	9
Applications	9
Product Care	10
Product Warranty	10
Product Disposal and Recycling	
Product Support	

## Introduction

Thank you for purchasing your R9400 Carbon Monoxide Meter with Temperature. Please read the following instructions carefully before using your instrument. By following the steps outlined in this manual your meter will provide years of reliable service.

## **REED Instruments**

## **Product Quality**

This product has been manufactured in an ISO9001 facility and has been calibrated during the manufacturing process to meet stated product specifications. If a certificate of calibration is required please contact the nearest authorized REED distributor or authorized Service Center. Please note an additional fee for this service will apply.

### Safety

Never attempt to repair or modify your instrument. Dismantling your product, other than for the purpose of replacing batteries, may cause damage that will not be covered under the manufacturer's warranty. Servicing should only be provided by an authorized service center.



Carbon monoxide (CO) can be life threatening even at relatively low concentrations. Do not use this meter as a personal safety monitoring device.

For safety reasons, we recommend that this unit be certified every year.

Effects of Carbon Monoxide (CO) Poisoning	
0 to 1 ppm	Normal background levels
9 ppm	ASHRAE Standard 62-1989 for living areas
35 ppm	The average exposure level per U.S. OSHA workplace standards
50 ppm	OSHA enclosed space 8-hour average level*
100 ppm	OSHA exposure limit*
200 ppm	Mild headache, fatigue, nausea and dizziness
400 ppm	Headache occurs in 2.5 to 3.5 hours
800 ppm	Dizziness, nausea and convulsions, Death within 2 to 3 hours

<sup>\*</sup>U.S. Department of Labor, Occupational Safety & Health Administration (OSHA) Regulation 1917.24: The CO content in any enclosed space shall be maintained at not more than 50 ppm (0.005%). Remove employees from enclosed space if the CO concentration exceeds 100 ppm (0.01%).

### **REED Instruments**

### **Features**

- · BacklittLCD bisplays to Offevels from bit off 000ppm and bient to temperature
- \* MUser #Edjustable \* Marm #mit #audible \* Beep #requency #mcreases \* Beep \* Beep #mcreases \* Beep \* Beep #mcreases \* Beep \* Beep #mcreases \* Beep
- · IIQuick II esponse and Inightaccuracy
- Data 

  Bold 

  Band 

  Bana 

  Bunctions
- · #Self#est #sequence #bn #start-up
- Low battery and cator and auto shut off

## **Specifications**

### Carbon Monoxide

Measuring Range: 1 to 1000 ppm Accuracy:  $\pm 5\%$  or  $\pm 5$  ppm

Resolution: 1 ppm

Sensor Type: Stabilized electrochemical sensor

Temperature

Measuring Range: -4 to 158°F (-20 to 70°C)

Accuracy:  $\pm 1.5^{\circ} F (0.8^{\circ} C)$ Resolution:  $0.1^{\circ} F (0.1^{\circ} C)$ Sensor Type: Thermistor

General Specifications

Display:

4-digit, ₩ual LCD

Backlit Display: Yes F/C Switchable: Yes

Alarm: Audible (buzzer)
Alarm Limit: User Adjustable

Max Hold: Yes
Display Hold: Yes

Warm-up Time: 60 seconds

continued.

### **REED Instruments**

Response Time: 2x per second
Auto Shut-off: Yes (after 30 mins, off)

Power Supply: 4 AA batteries
BatteryLife: Approx. 200 Mours

Low Battery Indicator: Yes
Product Certifications: CE

Probellength: 16" 406mm)

Operating Temperature: 32 to  $122^{\circ}F$  (0 to  $50^{\circ}C$ ) Storage Temperature: 14 to  $140^{\circ}F$  (-10 to  $60^{\circ}C$ )

Operating Humidity Range: 10 to 90%

Dimensions:图 7.5肽型.6肽器.7"間190肽胎5肽器5mm)

Weight: 8.3oz (235g)

## Included

- Soft Carrying Case
- Batteries

**REED Instruments** 


# **Instrument Description**

- 1. Sensor
- 2.8 LCDScreen
- 3. Data Hold Button
- 4. MAX/Down Button
- 5. Power Button
- 6. Battery Cover
- 7. Set Alarm Button
- 8. Backlight Button
- 9. Unit of Measure/Up Button



# **Display Description**

- 1. Auto Power Off Indicator
- 2. MAX Indicator
- 3. Data Hold Indicator
- 4. Beeper Off Indicator
- 5. Unit Indicator
- 6. High Alarm Indicator
- 7. Unit Indicator
- 8. Temperature Reading
- 9. SET Alarm
- 10. Alarm Indicator
- 11. CO Reading
- 12. Battery Capacity Indicator



## **REED Instruments**

## **Operating Instructions**

- Push the Power button to turn the meter on. To turn the meter off, press and hold the Power button until the meter counts down from 3 to 0
- 2. When turning the meter on it will perform a self-diagnostic test.
  During間he間est關he配CD剛iillԽount閾own閘rom酚0間o颲.찞nce閱he園
  meter passes the self-test a beep will sound and the meter will begin
  taking measurements. If the meter does not pass the self-test the
  LCD剛iill閾isplay閾Err"閾nd閱he勵meter刪iill勖ot闊ake閾勵neasurement.

### Unit of Measure Selection (Temperature)

When the meter is powered on press the  ${}^{\circ}\mathbf{C}/{}^{\circ}\mathbf{F}$  button to toggle between Celsius and Fahrenheit.

**Note:** The default unit of measure is Celsius (°C). The meter will automatically save the last selected unit of measure when turned off.

#### Data Hold

Press the **HOLD** button to freeze the current reading on the display. Press the button again to resume normal operation.

**Note:** When the Data Hold function is enabled the Max and °C/°F buttons are disabled.

### Setting the Alarm Threshold

- I. Press and hold the **SET** button to set the CO High Alarm Threshold.
- 2. While holding the **SET** Button, press the Up and Down buttons to adjust the the lalue.
- 3. Release the **SET** button to save and resume normal operation.

continued.

**REED Instruments** 

### MAX Function

- When pressing the MAX button once, the MAX Indicator will appear on the display. The maximum values (temperature and carbon monoxide) are displayed and will automatically update when new maximum data values are measured.
- Press the MAX button again and the MAX indicator will blink continuously. The Maximum values will automatically update in the Max memory while the current temperature and humidity measurements are displayed. To view the Max measurements during this mode press the MAX button at any time to access stored values.
- To exit MAX mode and resume normal operation, press and hold the MAX button for two seconds.

### Auto Power Off

To preserve battery life, the meter is programmed to turn itself off after 30 minutes of inactivity. To disable this feature, press and hold the **HOLD** button while powering on the meter. When the meter turns on, release both buttons simultaneously. The Auto Power Off indicator will not appear on the display, confirming this feature is now disabled. If the meter is t

### Backlight

PressMheBacklightButtonHoHurnHheLLCDBacklightBnBandBff.


### Beener Off

To turn the beeper off, press and hold the Backlight button while powering the three terms. The Beeper off and icator will appear to the confidence of the back on, the beeper will be enabled again.

**REED Instruments** 

## **Battery Replacement**

- Loosentheticrewthtthetiottomthetinetertheticletheticovertal away from the meter.
- 2. Replace the four (4) AA batteries.
- 3. Reinstall the battery door and tighten the screw to fasten in place.



# **Accessories and Replacement Parts**

CA-05A Soft Carrying Case

Don't see your part listed here? For a complete list of all accessories and replacement parts visit your product page on www.reedinstruments.com.

## **Applications**

- MResidential and Commercial safety
- Werifying Murnaces, Cookers, Water Coilers and Cas Moom Theaters

**REED Instruments** 

### **Product Care**

To keep your instrument in good working order we recommend the following:

- · IIStoreWourfbroductIntablean, blry blace.
- · MChange The Boattery Bas Sheeded.
- If Byour Instrument Isn't Ibeing Ibsed Ior Ib Beriod Ibf Ibne Imonth Ibr Illonger Ibplease remove the battery.
- \*\*CleanWourthroducthandhaccessories\*\*withthiodegradable\*\*Leaner.\*\*Dothothather spray the cleaner directly on the instrument. Use on external parts only.

### **Product Warranty**

REED Instruments guarantees this instrument to be free of defects in material or workmanship for a period of one (1) year from date of shipment. During the warranty period, REED Instruments will repair or replace, at no charge, products or parts of a product that proves to be defective because of improper material or workmanship, under normal use and maintenance. REED Instruments total liability is limited to repair or replacement of the product. REED Instruments shall not be liable for damages to goods, property, or persons due to improper use or through attempts to utilize the instrument under conditions which exceed the designed capabilities. In order to begin the warranty service process, please contact us by email at 1-877-849-2127 or info@reedinstruments.com to discuss the claim and determine the appropriate steps to process the warranty.

## **Product Disposal and Recycling**



Please follow local laws and regulations when disposing or recycling your instrument. Your product contains electronic components and must be disposed of separately from standard waste products.

**REED Instruments** 

# **Product Support**

If you have any questions on your product, please contact your authorized REED distributor or REED Instruments Customer Service by phone at 1-877-849-2127 or by email at info@reedinstruments.com.

Please visit www.REEDINSTRUMENTS.com for the most up-to-date manuals, datasheets, product guides and software.

Product specifications subject to change without notice. All rights reserved. Any unauthorized copying or reproduction of this manual is strictly prohibited without prior written permission from REED Instruments.

**REED Instruments** 





# **CHECK OUT OUR LATEST PRODUCTS!**

**REED Instruments**